



ORIGINAL ISSUE DATE: September 7, 2004

PROGRAM ADMINISTRATOR  
DEPARTMENT ALECP  
INTERTEK  
ETL SEMKO Division  
3933 U.S. ROUTE 11  
CORTLAND, NY 13045-0950

Recertification due: May 2012

An Activity Sponsored and Administered by  
Intertek

CROUSE HINDS AIRPORT LIGHTING  
PRODUCTS  
1200 Kennedy Rd.  
Windsor, CT 06095

**AIRPORT LIGHTING  
EQUIPMENT  
CERTIFICATION PROGRAM**

**CERTIFICATE OF  
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Advisory Circular 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program" issued by Federal Aviation Administration. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Administrator of the results of such tests, accompanied by related documents, by an Intertek recognized testing laboratory.

1. The listing below will be added to the next published Directory.

L-807 – Wind Cones, Rigid (AC 150/5345-27D)				
Manufacturer	Size	Manufacturer's Catalog Number		
		Lighted		Unlighted
		Style 1A External	Style 1B Internal	
Crouse Hinds ALP	1	44481(276)(277)		44482
	1	44483(276); 44484(277)		
	2	48310(276)(277)		48311
	2	48312(276); 48313(277)		
NOTE: Lamp (276) 150/CL RF Option, 150W, 120V GE; Lamp (277) 10047-2882 Floodlight, 250W, 120V GE Par-38				

2. This Certification requires continuing validation in accordance with the requirements of the Advisory Circular noted above and the Intertek Airport Lighting Equipment Certification Program. Confirmation of current certification may be obtained at [www.faa.gov/arp/arphone.cfm](http://www.faa.gov/arp/arphone.cfm)

3. Product tested and Report issued by: Intertek

(A) Report No: 3052996-001

(C) FAA Specification No.: AC No. 150/5345-27D

(B) Date of Report: 5/2004

(D) Date of Receipt of Report by the Administrator:  
August 2004

Approved for Certification by:

NOTE: PLEASE REVIEW, AND ADVISE  
ADMINISTRATOR AT INTERTEK IMMEDIATELY  
IF DATA, AS SHOWN, NEED TO BE  
CORRECTED.

David C. Edwards, Program Administrator  
Date: September 7, 2004