



REVISION DATE: April 30, 2009

ORIGINAL ISSUE DATE: August 6, 2003

Recertification due: August 2010

PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

An Activity Sponsored and Administered by
Intertek

CROUSE HINDS AIRPORT LIGHTING
PRODUCTS
1200 Kennedy Rd.
Windsor, CT 06095

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacements parts or non-production components.

L-858 – Signs, Runway and Taxiway (AC 150/5345-44H)						
Manufacturer	Type	Size	Style	Class	Mode	Manufacturer's Catalog Number
Crouse Hinds ALP	L-858 Y, R, L	3	5	1	2	60915-4 (115); 62055-4 (117)
	L-858 Y, R, L	3	5	1	2	60915-6 (116); 62055-6 (116)
	L-858 Y, R, L	3	5	1	2	60915-8 (115); 62055-8 (117)
	L-858 Y, R, L	3	5	1	2	60915-10 (116); 62055-10 (117)
	L-858 B	5	5	1	2	60915-D (115); 62055-D (117)
	L-858 B	4	5	1	2	858BF-XX (117)

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.

2. Product tested and Report issued by: Intertek

(A) Report No: 3029669-001; 2320; 3029669-002;
3071045-LTR; 3166002CRT-001

(B) Date of Report: 8/2003; 7/2003; 12/2004; 2/2005;
4/2009

NOTE: PLEASE REVIEW, AND ADVISE
ADMINISTRATOR AT INTERTEK IMMEDIATELY
IF DATA, AS SHOWN, NEED TO BE
CORRECTED.

Approved for Certification by:

Jeremy N. Downs, PE, Program Administrator

Date: April 30, 2009

